





Aquifer Vulnerability

Ringaskiddy Resource Recovery Centre

238129-00 January 2016 Figure 13.11